# Gordon Playground Inspections up **PSSLive**<sup>+</sup>

10 The Beeches, Bangor BT19 7RF 27 Clos Cae Pwll, Nelson, Treharris CF46 6LA Phone: 07818 426651 Email: info@gordoninspections.co.uk Inspected by: Louisa Hill RPII Accreditation: 1067A

Annual Inspection 2024 Scott Park - Field and Gym Patchway Parish Council





#### **REPORT INTRODUCTION**

#### This information forms an integral part of the inspection report.

This report does not replace a site Risk Assessment. A site Risk Assessment is a legal requirement and the duty to undertake this lies with the operator. This report may form part of the full assessment.

EUROPEAN STANDARDS The equipment has been inspected in accordance with the most recent version of the relevant British and European Standard:

BS EN 1176:2017 (Parts 1,2,3,4,6)	Playground equipment and surfacing
BS EN 1176:2019 (Part 5)	Playground equipment and surfacing
BS EN 1176:2020 (Part 7)	Playground equipment and surfacing
BS EN 1176:2014 (Parts 11)	Playground equipment and surfacing
BS EN 1177:2008	Impact absorbing playground surfacing
BS EN 14974:2019	Skateparks
BS EN 15312:2007+A1 2010	Free access multi-sports equipment
BS EN 16630:2015	Outdoor fitness equipment
BS EN 16899:2016	Parkour equipment

British and European Standards are not a legal requirement in the UK however they represent best practice guides for owners and operators of equipment. In the event of a claim, compliance (or not) with the relevant standard is often the first port of call for the legal profession in establishing if the operator has fulfilled their Duty of Care' to users of the facility.

The Standards are regularly updated and the existing standards are withdrawn. There are a number of circumstances where, due to changes, equipment may fail the most up-to-date standards but this does not mean that the equipment is dangerous or that remedial action is required. It should be noted that standards are not retrospective.

During an inspection, irrespective of the age of the equipment, the inspector will always inspect to the most recent standard requirements. Any compliance failures will be noted, risk assessed and comment made as to whether any further action is required. Making changes to the design of a piece of equipment to try and eradicate a compliance failure may lead to a greater hazard being introduced.

#### INSPECTION METHODOLOGY

All inspections are undertaken by an appropriately trained and accredited Register of Play Inspectors International (RPII) inspector following the RPII Inspection Scope Document. Each inspector has been checked through the Disclosure and Barring Service (DBS) to the Enhanced level.

#### Inspections are undertaken in a systematic and logical manner:

- On first view of the site, an initial impression of the site is noted.
- Commencing at the approach to the site, the pathways leading from the road to the site are inspected.
- The perimeter (fence, hedge) to the site is inspected and all the access points (gates, dog grids, stiles).
- The ancillary items (site furniture, signage, litter bins) and general surfaces are inspected.
- All items of play equipment and their associated safer surfaces are thoroughly inspected.
- Before leaving, a final overview of the site is undertaken to ensure that all items have been thoroughly inspected and all findings recorded.

Routine Inspection: This inspection enables the identification of obvious hazards that can result from vandalism, use or weather conditions. (broken parts or broken bottles)

Operational Inspection: This is a more detailed inspection to check the operation and stability of the equipment especially any wear.

Annual Inspection: This is carried out to establish the overall level of safety of the equipment, foundations and surfaces. It includes compliance with the relevant British and European standards, effects of weather. presence of rotting or corrosion and any change in the level of safety as a result of repairs. It should be noted that this inspection forms only part of the overall Annual Main Inspection detailed in EN 1176 that should be carried out by the operator of the facility.

Post Installation Inspection: This is carried out immediately following the installation of a site or piece of equipment to establish the overall level of safety of the installation. It includes the equipment, foundations and surfaces, assesses the layout of the site and compliance with the manufacturers installation instructions and the relevant dimensional requirements of the British and European Standards.

Post-Accident, Post-Incident, Ad-Hoc, etc. Inspection: These specific inspections are generally carried out as a result of a specific incident or in relation to a specific piece of equipment. The inspection is modified as necessary.

All inspections are hands-on physical inspections during which all visible components are pulled, pushed and shaken. All inspections are non-dismantling and do not use ladders to gain access to high components, the inspector will however climb over the equipment as per its intended use. Inaccessible components (e.g. high beams, swings etc.) are additionally visually inspected with the use of a magnifying, illuminated mirror on a telescopic pole.

Inspection of the surfaces is visual in relation to the dimension requirements and overall condition. Impact attenuation is not tested, however, should the inspector feel that the surface may be inadequate and requires formal testing, this will be noted in the report.



Except where a loose-fill surface is installed, the inspection does not involve the inspector digging through the safer surface to examine the foundations of the equipment. Should the inspector feel that a further underground inspection is required, this will be noted in the report.

The inspection reflects the condition of the equipment at the time of the inspection. It is a snapshot in time and does not negate the need for a comprehensive inspection and maintenance regime to be undertaken by the operator as recommended in the relevant British and European Standard and by the manufacturer.

It should be noted that the condition and structural integrity of equipment can change rapidly as a result of prevailing weather conditions, usage and abuse.

Inspections do not include the inspection or testing of water supplies or electrical installations.

Photographs are taken as part of all inspections. Care is taken to ensure that these do not include identifiable images of children. If the inspector is unable to take photographs due to the number of children present this will be noted in the report. For all new findings at least one photograph will be taken to clearly illustrate the issue. For any unresolved findings from previous inspections, photographs will be taken to show deterioration or change. For Annual and Post Installation Inspections photographs of each asset will be taken. In some circumstances where there are multiple instances of the same finding on an asset then indicative photographs will be taken and appropriate notes provided - there may not be a photograph of every instance of the finding.

Any items that are not items of play equipment e.g. sculptures etc. will be visually inspected for condition and stability.

As part of Post Installation and Annual Inspections, the overall location, layout and design of the site is assessed and any issues recorded. These may include nearby features (roads, water, electricity cables/pylons, electrical installations), desire lines running across the path of moving equipment, other clashes of movement in and around the playground or lack of segregation by age.

Timber components are tested to aid identification of rot. Techniques using rubber mallets (resonance testing) and fine probes are employed to do this. Inaccessible high beams (swings, trim trails) are additionally visually inspected with the use of a magnifying, illuminated mirror on a telescopic pole.

By its very nature, timber is prone to cracking, these cracks will be identified as part of the inspection but may not require any action other than monitoring. Cracks which have the potential to be an entrapment or those that have penetrated deeper into the timber potentially compromising the effectiveness of the pressure treatment preservative will be identified and appropriate action recommended.

Inappropriate use of strimmers to the base of timber components can cause significant damage to the outer layers of the wood and compromise the effectiveness of the pressure treatment preservative. This type of damage will be identified in order that preventative action can be taken.

In recent years there has been increased concern regarding the presence of lead in paint used on childrens playground equipment. However, most modern metal playground equipment is coated with paint that does not contain lead.

Paint produced before 1980 is likely to contain a high lead content. However equipment coated with such paint does not present a hazard if it is in good condition. Thus equipment is checked to ensure that the coatings are in good condition and recommendations made accordingly.

Wear to shackle pins on swings is difficult to detect on non-dismantling inspections. Checks are made to identify excessive movement in the D shackle and where dry bearings are obvious. Whilst this action can identify serious defects it does not preclude the possibility in rare circumstances, of shackle pin failure. It is recommended that random inspection by removal of the D shackle pin be carried out as a regular maintenance feature.

All chain components are inspected for wear, particularly where a connector is used or at points that are subject to greater movement. Special attention is given where there is a difference in the materials used e.g. a stainless steel connector is used on a mild steel chain as these combinations will lead to accelerated wear. Generally wear on chains and connectors is identified early and flagged for monitoring, chains and connectors should be changed at 40%-50% wear. Wear on chain links may lead to chains failing the relevant entrapment test, however, the risk associated with this is low and most can remain in use until they reach the above level of wear.

Sealed for life parts are, by their very nature, particularly difficult to inspect. However any excessive movement or obvious signs of wear or damage identified will be reported accordingly.

The standards require a manufacturers label to be affixed to all equipment. This label must state the manufacturers details, year of manufacture, product name/reference and EN certification. Prior to 1999 very few manufacturers affixed a label to their products and more generally these labels are easily damaged or removed. As this is not detrimental to the equipment and does not influence the operational safety of the equipment, apart from during a Post Installation Inspection of new equipment, it is our policy not to record this failure within our reports.

Likewise the requirement within British and European Standards to have a ground level marked on items will not be reported unless a ground clearance failure is present or the issue is identified during a Post Installation Inspection.

There are various requirements for signage included in the British and European Standards. These relate to both site signage and in some cases specific usage signage on equipment. Any failure in these will be identified as standards failures as part of Post Installation and Annual Inspections and as maintenance issues as part of Routine and Operational Inspections.

The inspection provides a comprehensive statement of the condition of the site at the time of the inspection and therefore there may be findings recorded that do not currently require any action to be taken but the operator should be aware of these in order to monitor them for deterioration that will lead to action being required in the future. Likewise, findings may reflect issues that do not present a hazard e.g. minor surface rust but if action is taken in an appropriate timescale further deterioration may be prevented.

Inspections are recorded using an electronic asset management and inspection system. Wherever possible the inspections are completed live on site and synchronised into our cloud servers, from where the final report can be generated. Where available, previously reported findings that remain unresolved will be checked and re-risk assessed to highlight any changes in the time elapsed since they were first reported. These findings appear under a separate heading in the report.

Each finding is given a Cause eg Wear and Tear, Vandalism. This information can be useful for forward planning and tracking instances that may require input from other authorities such as the police.

The final report will also include an Asset List which includes information relating to manufacturer details (where possible), an expected End of Life Date, an overall Condition, an Age Range of the equipment and a Compliance with the relevant EN standard.

**RISK ASSESSMENT AND URGENCY (Resolve by Date)** 

A risk assessment of each finding is provided to assist the operator in determining the level of the hazard found.

The risk assessment utilises the 5 x 5 quantitative methodology and risk is assigned as a product of probability and severity.

**Risk Score = Probability X Severity** 

A final qualitative risk rating of high, medium or low is then obtained from an outcome matrix based upon the calculated risk score.

**Risk Score** 

The following tables give examples of the factors, which may be considered to determine the appropriate levels of probability and severity utilised in the calculation of quantitative risk scores. Examples indicated are not exhaustive.

Probability Score	Probability of Occurrence	
1 - Very Low	No significant probability	
	Lightning Strike	
2 – Low	Minimal probability of occurrence. Requires significant factor	
	or combination of factors to take place	
	<ul> <li>Significant increase in intensity of use.</li> </ul>	
3 – Moderate	Moderate probability. An added factor is needed to cause an	
	Accident. Designed use is unlikely to be problematic, additional	
	Factor is required.	
	<ul> <li>Covers or guards loose, removed or vandalised</li> </ul>	
	<ul> <li>Absent guard rail or barrier at high levels</li> </ul>	
4 – High	High probability. Accident is probable without any added	
	factor.	
	<ul> <li>Glass contaminant in loose fill surface</li> </ul>	
	<ul> <li>Exposed sharp edges on equipment</li> </ul>	
5 – Very High	Very High probability. If the situation is not addressed an	
36 T	accident is almost certain.	
	<ul> <li>Severely worn chains / shackles</li> </ul>	
	<ul> <li>Severely damaged surfacing within impact area</li> </ul>	

Severity Score	Severity of injury
1 – Very Low	No injury likely e.g. damaged or soiled clothing, minor bruising
2 – Low	Minor injury – Laceration or bruising requiring first aid only
3 – Moderate	Injury requiring medical intervention e.g. laceration requiring stitches, sprain, fracture of small bones of hand or foot.
4 – High	Serious injury including hospitalisation for observation e.g. concussion, fracture of long bones of leg/arm, back/neck injuries, fractured skull
5 – Very High	Severe injury involving the potential for permanent disability e.g. amputation, loss of sight, spinal injury, fatality.

#### **Risk Rating**

Having obtained a risk score the qualitative risk rating is obtained using the following matrix.

	5	1 x 5 = 5 LOW	2 x 5 = 10 MEDIUM	3 x 5 = 15 MEDIUM	4 x 5 = 20 HIGH	5 x 5 = 25 IMMEDIATE
	4	1 x 4 = 4 LOW	2 x 4 = 8 LOW	3 x 4 = 12 MEDIUM	4 x 4 = 16 HIGH	5 x 4 = 20 HIGH
SEVERITY	3	1 x 3 = 3 V LOW	2 x 3 = 6 LOW	3 x 3 = 9 LOW	4 x 3 = 12 MEDIUM	5 x 3 = 15 MEDIUM
SEVE	2	1 x 2 = 2 V LOW	2 x 2 = 4 LOW	3 x 2 = 6 LOW	4 x 2 = 8 LOW	5 x 2 = 10 MEDIUM
	1	1 X 1 = 1 V LOW	2 x 1 = 2 V LOW	3 x 1 = 3 V LOW	4 x 1 = 4 LOW	5 x 1 = 5 LOW
		1	2	3	4	5
	PROBABLITY					

#### Timescale for Action (Resolve by Date/Urgency)

Each finding will be given a timescale for action to be undertaken (Resolve by Date/Urgency). *These dates are advisory*. The timescales are primarily based on the risk associated with the finding - higher risks having shorter timescales; however there are some very low risk findings that would be considered socially unacceptable e.g. offensive graffiti or litter, these may also have shorter timescales. In addition some lower risk findings may be assigned a shorter timescale as swift action may prevent further deterioration.





# Inspection Scope for RPII Annual Inspectors

This document outlines the RPII scope for inspections undertaken by the Inspectors listed as Annual Inspectors on the RPII Register of Inspectors when undertaking Indoor Annual, Outdoor Annual, Outdoor Operational and Outdoor Routine inspections.

Inspections are undertaken with reference to the standards listed in this preamble only; where no date for the standard is given it will be the standard that is current at the time of inspection except where overlap periods are granted by the standards committee when standards are updated. The information contained in reports is provided to assist the owner/operator in fulfilling their responsibilities as detailed in the relevant standard. Other standards referenced within the listed standards do not form part of the inspection, unless they are also explicitly listed here.

The following standards are relevant to all installations of equipment that are publicly accessible to users; this includes public parks, pay and play parks, schools, nurseries, public houses, holiday parks, indoor play centres, farm parks etc. All equipment used or employed in publicly accessible areas should meet with the requirements of the relevant standards (listed below):

BS EN 1176 Parts 1, 2, 3, 4, 5, 6, 10 & 11 Playground equipment intended for permanent installation outdoors & indoors.

BS EN 1176 Part 7 - 'Guidance on Installation, Inspection, Maintenance and Operation' (this document gives guidance to the owners/operators of the facility on the installation, inspection, maintenance and operation of playground equipment, excluding ancillary items).

In the United Kingdom the National Foreword forms an important part to the understanding and implementation of the recommendations set out in this document. It clarifies the application of the document within the UK as best practice guidance, as the document has been used since its initial publication. Therefore, in the UK this standard (BS EN 1176 – Part 7) contains no requirements and needs to be read and implemented as guidance, with the use of the term 'shall' therefore becoming a recommendation, as in the term 'should'.

Domestic play equipment falls outside of the scope of BS EN 1176 and has its own standards (BS EN 71 series – Safety of Toys). Where domestic equipment can be identified this will be acknowledged in the report but any comments concerning compliance will follow the requirements and recommendations of BS EN 1176.

When water play items, including spray parks, are inspected any comments concerning compliance within the inspection will refer to EN 1176. We have not assessed these against the requirements of EN 17232 (Water play equipment and features).

Other equipment that is not clearly identified as unsupervised or domestic (natural play, self-build equipment etc.) will be assessed for compliance with the relevant standard listed below:

BS EN 15312 Free access multi-sports equipment BS EN 14974 Skateparks BS EN 16630 Permanently installed outdoor fitness equipment BS EN 16899 Parkour equipment (plus RPII/API guidance notes)

Annual and Post Installation inspections will take into consideration compliance with these current standards, and defects related to wear and vandalism. Items not listed in the report have not been included in the inspection. The inspection will cover the playground equipment and the active area (that area which is obviously part of the playground), nominally up to three metres around, the fence line if closer, or other areas as agreed.

Operational inspections only take into consideration defects related to cleanliness, equipment ground clearances, ground surface finishes, exposed foundations, sharp edges, missing parts, excessive wear (of moving parts) structural integrity, wear and vandalism.

Routine visual inspections relate only to the most obvious defects such as broken or missing parts, litter. vandalism and issues created by severe weather conditions (the intention is to identify hazards created by storm damage).

All inspections are non-dismantling, non-destructive and do not include any structural, toxicology or impact assessments defined in the standard; however, the inspector will undertake a manual test for stability and if equipment fails under manual load, or any other hazard is identified as an unacceptable risk, the owner/operator will be notified as soon as practicably possible.

The inspector will access all reasonably accessible equipment and will assess all reasonably accessible parts above the standing surface. Where it is not possible to access parts of the equipment without employing an alternative means of access the report will record the action required by the owner/operator to ensure the continued safe use of the equipment.

Ancillary equipment will be assessed using the inspector's knowledge and experience of the standards named in this document. (Note: Ancillary items are not included in the specific equipment-type parts of the EN 1176 series; hence they are not assessed for compliance with EN 1176 series and are subject to a general safety assessment).

The owner/operator is responsible for the overall safety of the equipment and area.

The inspector will not undertake any of the following works unless specifically agreed in writing at the time of order:

Checking the depth and underlying structural integrity of any surface areas and/or carrying out any testing of the impact attenuating properties of any surfaces; the identification of any corrosion, rot or other deterioration in any apparatus or equipment other than by an external inspection; the inspection of any equipment (or part thereof) that is beneath the playing surface (loose-fill materials may be moved to expose foundations); tightening any bolts, hinges or other fixing devices on any apparatus or equipment; assessing or inspecting any electrical installations contained on any site and/or apparatus and/or equipment; assessing or inspecting any water supplies and/or water features and/or any associated computerised systems (including carrying out any programming); where planting or trees are mentioned in the report no assessments of toxicity, suitability or condition are undertaken – the owner/operator should have suitable inspections provided by a competent person.

The owner/operator should have a 'design risk assessment' provided by the manufacturer/designer of the area for the equipment and location in which the facility is installed.

The operator is responsible for managing risks of their provision and is required by law to carry out a 'suitable and sufficient assessment' of the risks associated with a site or activity. This inspection shall be considered as contributing to the operator's discharge of this responsibility.

The details contained within the report are a snapshot of the condition at the time of inspection only and subsequent events may affect the condition of the facility. Suggested remedial actions are based on the knowledge and experience of the inspector and/or that of the inspection company. The owner/operator should always seek the advice of the manufacturer or a competent person when undertaking repairs and/or modifications to equipment.



#### Table 1

The operator is responsible for following the guidance of the relevant standards. The standards give guidance on the installation, inspection, maintenance and operation of the various types of facilities. The inspection guidance is listed in Table 1, with an indication of which parts will be included in an RPII Annual or Post-Installation Inspection. The relevant standards also contain additional parts which the operator should follow.

Inspection Recommendations of relevant standards Refer to relevant standards for full text	Annual Main	RPII Annual/ Post Installation Inspection
6.1 d) Overall levels of safety of equipment (see note 1)	-	✓[1]
6.1 d) Overall levels of safety of foundations (see note 1)	-	✔[1]
6.1 d) Overall levels of safety of playing surfaces (see note 2)	~	✔[2]
6.1 d) Compliance with the relevant parts of the standard and or risk assessment (see note 3)		✔[3]
6.1 d) Effects of weather	~	~
6.1 d) Presence of rot, <u>decay</u> or corrosion (see note 1)	~	✔[1]
6.1 d) Assessment of repairs made or added or replaced components (see note 4)	-	✔[4]
6.1 d) Excavation or dismantling/additional measures	~	×
6.2.1 Assessment of glass reinforced plastics (see note 5)	~	✓[5]
6.2.1 Inspection of one post equipment (see note 1)	~	✔[1]
6.2.4 Undertaking the Operators inspection protocol	~	×

NB: The clause numbers in table 1 are taken from BS EN 1176 - Part 7:2020. The content is equally applicable to all other relevant standards listed herein. Playgrounds contain a range of equipment from different manufacturers and installed over a number of years; operators should implement any guidance provided by the manufacturer. Item specific detail is not readily available to RPII Playground Inspectors, whose report contributes to the operator's overall Annual Main Inspection as detailed in the relevant

[1] A manual test only is undertaken for stability. Wear and instability are only detectable where readily apparent without dismantling or destruction and without the use of tools, excavation or specialist equipment. Rot and corrosion are tested or with a hammer and/or steel rod. Decay in timber may exist which can only be found with specialist equipment.

[2] Only the visible condition and dimensional compliance of surface extent is considered. Neither testing of impact attenuating properties nor measurement of the thickness of bound surfaces are undertaken on RPII annual inspections.

[3] The inspection assesses compliance where this can be tested on site using manual methods without dismantling, destruction and without the use of tools or specialist equipment.

[4] The operator should use manufacturer's recommended parts, or equivalent. We are unable to verify if such parts have been used, and any subsequent change in quality or performance.

[5] Visible glass fibres will be noted in reports. The operator is responsible for repairs or replacement.



## **Inspection Report**

This report shows Findings and Tasks recorded during the Inspection(s) matching the selection criteria set in the Report Wizard. If no Findings or Tasks are shown, none were recorded.

# Each Inspection includes a declaration signed by the Inspector stating that no defects were found other than those recorded.

#### Inspections included in this report

Site Name	Scott Park - Field and Gym	
Inspection Type	Playground-Annual	
Actual Date	04/10/2024 14:40:18	
Inspector	Louisa Hill	
		04/10/2024



# **Finding Summary**

#### Scott Park - Field and Gym Findings

Asset	Finding Title	Creation Date	Resolve By Date	Risk Level
Field - Rocker Motorbike	Foot Rests - Shape	14/10/2019 13:30:00	24/09/2024 10:19:09	Low
Field - Rocker Motorbike Surface	Ground Eroded	04/10/2024 14:47:34	27/12/2024 13:47:54	Low
Gym - Cycle	Information for Use - Instructions	04/11/2020 17:00:00	28/11/2024 08:57:05	Very Low
Gym - Walker	Information for Use - Instructions	04/11/2020 17:00:00	06/05/2021 17:00:00	Very Low
Site	Information for Use - Signage	04/11/2020 17:00:00	27/09/2023 08:22:43	Very Low
Gym - Cycle	Item - Repair/s - Minor	18/10/2021 10:09:52	27/02/2024 14:01:09	Very Low
Field - Rocker Motorbike	Item - Cap missing	17/05/2022 10:09:17	15/05/2024 09:35:09	Very Low
Picnic Table - Blue	Item - Cracked	25/01/2023 14:25:43	23/05/2025 08:44:46	Very Low
Gym - Walker Surface	Ground Eroded	09/04/2024 10:26:03	24/09/2024 10:26:34	Very Low
Gym - Cycle Surface	Ground Eroded	04/10/2024 14:41:14	21/03/2025 13:41:38	Very Low
Field - Mini Tennis Court	Surface - Trip points	04/10/2024 14:43:03	21/03/2025 13:43:40	Very Low
Field - Goal Post Surface	Ground Eroded	04/10/2024 14:45:14	21/03/2025 13:45:27	Very Low

# Inspection - Scott Park - Field and Gym - 04/10/2024 14:40:18

Site Name	Scott Park - Field and Gym	
Inspection Type	Playground-Annual	- /   /   /   /
Actual Date	04/10/2024 14:40:18	
Inspector	Louisa Hill	
		04/10/2024

Site Name	Scott Park - Field and Gym	
Address	Coniston Road Patchway Bristol	
Postcode	BS34 5JR	

#### Scott Park - Field and Gym Inspected Asset List (see Inspection Notes for exceptions)

Asset Name	Field - Goal Post	Aller Aller a service
Asset Category	Equipment (Multi Sports)	A Star Star
Asset Type	Ball Play	
Asset Sub Type	Goal Post/s	and the second state of the second state
Manufacturer		
EN Compliant		
Age Ranges		State State
Asset Condition	Good	
Expected End of Life/Removed Date		- 04/10/2024

Asset Name	Field - Goal Post Surface	
Asset Category	Surface	
Asset Type	General Surface	
Asset Sub Type	Grass	
Manufacturer		
EN Compliant		
Age Ranges		
Asset Condition	Good	
Expected End of Life/Removed Date		27/08/2024

Asset Name	Field - Mini Tennis Court	
Asset Category	Equipment (Multi Sports)	ar as ar
Asset Type	Ball Play	1
Asset Sub Type	Tennis Court/s	
Manufacturer	Unknown	
EN Compliant	Yes	
Age Ranges	Toddler, Junior	
Asset Condition	Good	
Expected End of Life/Removed Date	31/03/2033	04/10/2024

	d - Rocker Motorbike
Accet Category	ipment (Outdoor Play)
Asset Category Equi	
Asset Type Rock	ker and a second se
Asset Sub Type Type	e 2A - Single Point - Unidirectional
Manufacturer Fahr	r Industries Ltd
EN Compliant No	
Age Ranges 0 - 2	2 Years, Toddler
Asset Condition Aver	rage
Expected End of Life/Removed Date 31/0	04/10/2024

Asset Name	Field - Rocker Motorbike Surface
Asset Category	Surface
Asset Type	Safer Surface
Asset Sub Type	Grass
Manufacturer	
EN Compliant	Yes
Age Ranges	
Asset Condition	Average
Expected End of Life/Removed Date	31/03/2033

Asset Name	Gym - Cycle	The second second second second second
Asset Category	Equipment (Outdoor Fitness)	
Asset Type	Outdoor Fitness (Gym Style)	- A
Asset Sub Type	Cycle	
Manufacturer	Outdoor Fitness Center - Starmax	
EN Compliant	No	
Age Ranges	Youth, Adult	
Asset Condition	Average	
Expected End of Life/Removed Date	31/03/2030	04/10/2024

Asset Name	Gym - Cycle Surface
Asset Category	Surface
Asset Type	Safer Surface
Asset Sub Type	Grass
Manufacturer	
EN Compliant	Yes
Age Ranges	
Asset Condition	Average
Expected End of Life/Removed Date	31/03/2033

Asset Name	Gym - Walker	
Asset Category	Equipment (Outdoor Fitness)	ALL AND A DE MAN
Asset Type	Outdoor Fitness (Gym Style)	The set
Asset Sub Type	Walker	
Manufacturer	Outdoor Fitness Center - Starmax	
EN Compliant	No	
Age Ranges	Youth, Adult	
Asset Condition	Average	The second s
Expected End of Life/Removed Date	31/03/2030	04/10/2024

Asset Name	Gym - Walker Surface	
Asset Category	Surface	
Asset Type	Safer Surface	a same and
Asset Sub Type	Grass	* Contraction of the second
Manufacturer		and the second second
EN Compliant	Yes	Concer Star Start T
Age Ranges		
Asset Condition	Average	and the second second
Expected End of Life/Removed Date	31/03/2033	08/01/2024
		00/01/2024

Asset Name	Picnic Table - Blue	
Asset Category	Facilities	A DECEMBER OF THE DECEMBER OF
Asset Type	Seating	
Asset Sub Type	Picnic Table	
Manufacturer		
EN Compliant		
Age Ranges		
Asset Condition	Average	
Expected End of Life/Removed Date	31/03/2030	04/10/2024

Asset Name	Picnic Table - Red	
Asset Category	Facilities	
Asset Type	Seating	Nº TO
Asset Sub Type	Picnic Table	
Manufacturer		
EN Compliant		and as a second second
Age Ranges		Contraction of the Association
Asset Condition	Average	1 4 4 B 1 1 1 10
Expected End of Life/Removed Date	31/03/2036	04/10/2024

Asset Name	Site	AND STORES
Asset Category	Site	
Asset Type	Site	I II III III
Asset Sub Type	The Overall Site	
Manufacturer		
EN Compliant		
Age Ranges		States and the second second
Asset Condition	Average	
Expected End of Life/Removed Date	31/03/2033	20/10/2023

# Findings and Tasks reported within the Inspection

#### Field - Goal Post Surface - Finding

Asset	Field - Goal Post Surface	
Finding Group	Maintenance	
Finding Title	Ground Eroded	
Standard Reference		
Standard Description	Ground eroded	
Finding Notes		and the second second
Cause	Wear and Tear	The second second
Finding Creation Date	04/10/2024 14:45:14	
Risk Value Text	1 x 2 = 2	Asset Photo
Risk Level	Very Low	
Resolve By Date	21/03/2025 13:45:27	
Finding Status	Open	



04/10/2024

#### **Ground Eroded - Task**

Task Title	Make good surface
Task Notes	
Task Status	Unapproved

#### Field - Mini Tennis Court - Finding

Asset	Field - Mini Tennis Court	
Finding Group	Maintenance	Star Box St. St.
Finding Title	Surface - Trip points	
Standard Reference		
Standard Description	Trip points	
Finding Notes		
Cause	Wear and Tear	
Finding Creation Date	04/10/2024 14:43:03	
Risk Value Text	1 x 3 = 3	Asset Photo
Risk Level	Very Low	ASSEL PIIOLO
Resolve By Date	21/03/2025 13:43:40	
Finding Status	Open	



#### Surface - Trip points - Task

Task Title	Repair surface	
Task Notes		
Task Status	Unapproved	




#### Field - Rocker Motorbike Surface - Finding

Asset	Field - Rocker Motorbike Surface
Finding Group	Maintenance
Finding Title	Ground Eroded
Standard Reference	
Standard Description	Ground eroded
Finding Notes	
Cause	Wear and Tear
Finding Creation Date	04/10/2024 14:47:34
Risk Value Text	2 x 4 = 8
Risk Level	Low
Resolve By Date	27/12/2024 13:47:54
Finding Status	Open



#### **Ground Eroded - Task**

Task Title	Make good surface
Task Notes	
Task Status	Unapproved




#### Gym - Cycle Surface - Finding

Asset	Gym - Cycle Surface
Finding Group	Maintenance
Finding Title	Ground Eroded
Standard Reference	
Standard Description	Ground eroded
Finding Notes	
Cause	Wear and Tear
Finding Creation Date	04/10/2024 14:41:14
Risk Value Text	1 x 3 = 3
Risk Level	Very Low
Resolve By Date	21/03/2025 13:41:38
Finding Status	Open



#### **Ground Eroded - Task**

Task Title	Make good surface
Task Notes	
Task Status	Unapproved



# Previously Reported Findings and Tasks (unresolved at time of Inspection)

#### Field - Rocker Motorbike - Findings

Asset	Field - Rocker Motorbike	LEE
Finding Group	Maintenance	and the second second
Finding Title	Item - Cap missing	al sub a state
Standard Reference		
Standard Description	Item - Cap missing	
Finding Notes	Rear wheel fixing cover	Sector Sector
Cause	Wear and Tear	
Finding Creation Date	17/05/2022 10:09:17	and the second second
Risk Value Text	1 x 3 = 3	Asset Photo
Risk Level	Very Low	
Resolve By Date	15/05/2024 09:35:09	
Finding Status	Closed	





**Finding Photos** 

12/10/2022

#### 17/05/2022

Item - Cap missing - Task	
Task Title	Replace item
Task Notes	Has now been replaced with new caps
Task Status	Completed

Asset	Field - Rocker Motorbike	C. C
Finding Group	BS EN 1176:2017 Part 6 (Rockers - Playground)	and the second second
Finding Title	Foot Rests - Shape	all such a second
Standard Reference	EN 1176:2017 - 6 - 4.6	
Standard Description	When tested in accordance with EN 1176 the ends of the foot rests do not comply with the requirements.	
Finding Notes	Now has brand new foot rests	and the second s
Cause	Manufacturer Defect	and the second second
Finding Creation Date	14/10/2019 13:30:00	
Risk Value Text	1 x 4 = 4	Asset Photo
Risk Level	Low	
Resolve By Date	24/09/2024 10:19:09	
Finding Status	Closed	



Task Title	No action required, based on risk assessment, as asset pre-dates BSEN1176
Task Notes	Now has brand new foot rests
Task Status	Completed

#### Gym - Cycle - Findings

Asset	Gym - Cycle	- All and a start of the start
Finding Group	Maintenance	
Finding Title	Item - Repair/s - Minor	0
Standard Reference		
Standard Description	Item needs minor repair/s	
Finding Notes	Pedal friction force adjuster is not working correctly.	
Cause	Wear and Tear	
Finding Creation Date	18/10/2021 10:09:52	Contraction of the state
Risk Value Text	1 x 3 = 3	Asset Photo
Risk Level	Very Low	ASSEL FILULO
Resolve By Date	27/02/2024 14:01:09	
Finding Status	Open	









12/10/2022

28/10/2021

04/10/2024
------------

20/10/2023





### ltem - Repair/s - Minor - Task

Task Title	Repair item
Task Notes	Advice to be obtained from manufacturer.
Task Status	Assigned

Asset	Gym - Cycle	Participant and an address of
Finding Group	BS EN 16630:2015 (Outdoor Fitness Equipment)	The second s
Finding Title	Information for Use - Instructions	1
Standard Reference	EN 16630 - 7.2	
Standard Description	The minimum instructions are not attached in a durable and clearly conspicuous form on or adjacent to each piece of equipment.	
Finding Notes		at a strength of the strength of the
Cause	Manufacturer Defect	Carl Carl Carl
Finding Creation Date	04/11/2020 17:00:00	
Risk Value Text	1 x 1 = 1	Asset Photo
Risk Level	Very Low	
Resolve By Date	28/11/2024 08:57:05	
Finding Status	Open	







28/10/2021

Information for Use - Instructions - Task	
Task Title	Modify to meet EN 16630.
Task Notes	Still needs instructions 25.1.23
Task Status	Assigned



#### Gym - Walker - Finding

Asset	Gym - Walker	A CONTRACTOR
Finding Group	BS EN 16630:2015 (Outdoor Fitness Equipment)	A STATISTICS
Finding Title	Information for Use - Instructions	The at
Standard Reference	EN 16630 - 7.2	The second second
Standard Description	The minimum instructions are not attached in a durable and clearly conspicuous form on or adjacent to each piece of equipment.	
Finding Notes		
Cause	Manufacturer Defect	The second second second
Finding Creation Date	04/11/2020 17:00:00	
Risk Value Text	1 × 1 = 1	Asset Photo
Risk Level	Very Low	
Resolve By Date	06/05/2021 17:00:00	
Finding Status	Open	



**Finding Photos** 



05/11/2020

Information for Use	- Instructions - Task
Task Title	Modify to meet EN 16630.
Teel: Netee	

Task Notes	
Task Status	Assigned

#### Gym - Walker Surface - Finding

-	-	
Asset	Gym - Walker Surface	
Finding Group	Maintenance	
Finding Title	Ground Eroded	
Standard Reference		
Standard Description	Ground eroded	
Finding Notes	Needs soil ongoing repairs	and the start of
Cause	Wear and Tear	
Finding Creation Date	09/04/2024 10:26:03	10 10 10 10 10 10 10 10 10 10 10 10 10 1
Risk Value Text	1 x 1 = 1	Asset Photo
Risk Level	Very Low	ASSEL PHOLO
Resolve By Date	24/09/2024 10:26:34	-
Finding Status	Open	-




Finding Photos



09/04/2024

#### Ground Eroded - Task

Task Title	Make good surface
Task Notes	
Task Status	Unapproved



#### Picnic Table - Blue - Finding

Asset Finding Group Finding Title Standard Reference Standard Description Finding Notes Cause Finding Creation Date Risk Value Text Risk Level	Picnic Table - Blue         Maintenance         Item - Cracked         Metal weld cracks         Welding joint cracked 25/1/23         Wear and Tear         25/01/2023 14:25:43         1 x 2 = 2         Very Low	Asset Photo
	1 x 2 = 2 Very Low	Asset Photo
Resolve By Date Finding Status	23/05/2025 08:44:46 Open	-









04/10/2024

Item - Cracked - Task

drached	ruon.
Task Title	Reweld
Task Notes	Needs welding
Task Status	Assigned
	Task Photos           17/05/2023



#### Site - Finding

Asset	Site	ALCONT THE
Finding Group	BS EN 16630:2015 (Outdoor Fitness Equipment)	
Finding Title	Information for Use - Signage	
Standard Reference	EN 16630 - 7.1	
Standard Description	An information sign displaying (all) the minimum information is not provided at equipment facilities in an easily conspicuous form.	f "
Finding Notes	Gym Area	and the second
Cause	Installation Defect	The second second
Finding Creation Date	04/11/2020 17:00:00	
Risk Value Text	1 x 1 = 1	Asset Photo
Risk Level	Very Low	
Resolve By Date	27/09/2023 08:22:43	
Finding Status	Open	



Finding Photos



05/11/2020

o meet EN 16630.
d